

Blessed Sacrament Church Campaign and Repair Update

May 2017

April showers bring...more leaks! The last heavy rain once again proved to us the extent of the needed repairs, with water leaking through open mortar joints in the church façade, down through the walls of the east choir staircase. While our Architect and Contractor continue to submit samples of replacement mortar and stone to the New York Landmarks Preservation Commission for approval, work is moving along. The initial phase of the brick pointing is underway on both the east and west sides of the church.